


NICE WHEEL

1) Calculate the NORTHINGS and EASTINGS for Points "A" thru "H".

Record all data on the chart provided.

2) Determine and Record the BEARINGS and DISTANCES for courses A-B, B-C, C-D, D-E, E-F, F-G, G-H & H-A.

SKETCH NOT TO SCALE



$$\text{Origin} = \frac{5,000.0000}{10,000.0000}$$